


95 Cantiague Rock Road, Westbury NY 11590 ph:516.931.9090 fax:516.931.1254 info@crystorama.com www.crystorama.com

MODEL#: 138-VZ ASSEMBLY AND DRESSING INSTRUCTIONS

IMPORTANT

TURN OFF THE POWER AT THE MAIN FUSE OR CIRCUIT BREAKER BOX BEF ORE STARTING INSTALLATION



B= 76mmx90sets (Spare parts: 3sets)

C= (40mm Ball with chain)x1set